Document 5 – COHETE

1. Import the file on the Slicing Software ("Cura") and orient the piece in the best way to be printed.



2. I enter all the correct printing parameters (layer height, wall tickness, infill, support, speed, temperature, ...) and check for any problems from the "Preview"



3. At this point I can save the ".Gcode" file to send to the machine.